

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	76	(33/538).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:22
L2	384	(33/534).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:59
L3	375	2 not 1	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:22
L4	1834802	bend or bending or bends or deflect\$ or strain\$ or stretch\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:57
L5	59	3 and 4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:23
L6	0	(33/in).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:50
L7	589	(33/1n).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:50
L8	61	4 and 7 not (1 or 5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:55
L9	1981	(73/432.1,865.8,865.1).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:55
L10	193919	(measur\$ or determin\$ or test or testing or tests) near5 angle\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:04
L11	135131	(detect\$ or sensor or sensing or senses) near5 angle\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:56

## EAST Search History

L12	73750	(monitor\$ or calculat\$ or comput\$) near5 angle\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:56
L13	318925	10 or 11 or 12	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:57
L14	120739	(bend or bending or bends or deflect\$ or strain\$ or stretch\$) near14 angle\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:57
L15	7	9 and 13 and 14	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 14:57
L16	469	(33/783,785,786,791).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:00
L19	1584	(324/207.25,207.32).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:01
L20	1128	(356/138).ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:01
L21	3180	16 or 19 or 20	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:01
L22	78	21 and 13 and 14 not (15 or 1 or 5)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:02
L23	193724	(measur\$ or determin\$ or test or testing or tests) near5 angle\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:03
L24	318743	23 or 11 or 12	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:03
L25	7	9 and 24 and 14	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:03

## EAST Search History

L26	0	25 not 15	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:03
L27	41479	(measur\$ or determin\$ or test or detect\$ or sense or sensing or calculat\$ or comput\$) near8 (displacement or length or distance) near25 angle	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:15
L28	15	22 and 27	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:08
L29	5016	neutral near1 axis	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:11
L30	153	13 and 14 and 29 not (1 or 5 or 15 or 25 or 28)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:15
L31	40	27 and 30	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:16
L32	4	"5772610".pn. or "6117091".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 15:20
L33	2	"5633494".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 16:09
L34	198909	(length or displacement or distance) near15 angle	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 16:10
L35	1	33 and 34	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 16:13
L36	25881	fiber near8 (strain\$ or stretch\$ or elongat\$)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 16:14
L37	1	33 and 36	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/03/05 16:14